

# SECURITIES AND EXCHANGE COMMISSION

## SEC FORM 17-C

### CURRENT REPORT UNDER SECTION 17 OF THE SECURITIES REGULATION CODE AND SRC RULE 17.2(c) THEREUNDER

1. Date of Report (Date of earliest event reported)  
May 18, 2017
2. SEC Identification Number  
ASO-95002283
3. BIR Tax Identification No.  
004-703-376
4. Exact name of issuer as specified in its charter  
DMCI Holdings, Inc.
5. Province, country or other jurisdiction of incorporation  
Philippines
6. Industry Classification Code(SEC Use Only)
7. Address of principal office  
3/F Dacon Bldg. 2281 Chino Roces Avenue, Makati City  
Postal Code  
1231
8. Issuer's telephone number, including area code  
(632) 888 3000
9. Former name or former address, if changed since last report  
N/A
10. Securities registered pursuant to Sections 8 and 12 of the SRC or Sections 4 and 8 of the RSA

Title of Each Class	Number of Shares of Common Stock Outstanding and Amount of Debt Outstanding
Common	13,277,470,000
Preferred	3,780

11. Indicate the item numbers reported herein  
Item no. 9

*The Exchange does not warrant and holds no responsibility for the veracity of the facts and representations contained in all corporate disclosures, including financial reports. All data contained herein are prepared and submitted by the disclosing party to the Exchange, and are disseminated solely for purposes of information. Any questions on the data contained herein should be addressed directly to the Corporate Information Officer of the disclosing party.*



# DMCI Holdings, Inc.

## DMC

**PSE Disclosure Form 4-31 - Press Release**  
**References: SRC Rule 17 (SEC Form 17-C)**  
**Section 4.4 of the Revised Disclosure Rules**

### Subject of the Disclosure

Press Release: DMCI Power helps avert Masbate power outages

### Background/Description of the Disclosure

DMCI Power helps avert Masbate power outages

Off-grid energy player DMCI Power Corporation (DPC), in partnership with the Masbate Electric Cooperative (MASELCO), recently replaced reclosers in the distribution line feeders located in PV Corpuz, Magsaysay, Buenavista and Mobo in the province of Masbate.

A recloser is a circuit breaker that automatically switches off power in a distribution line segment or section during power overload or line faults. It limits the impact of an outage by isolating the faulted section from the rest of the distribution system effectively curtailing a domino-effect of power line interruptions.

As a result of the installation, power supply interruption due to line faults has decreased significantly in the MASELCO service area.

Based on technical reports, around 47 line trippings were contained and isolated in the PV Corpuz feeder segments since March 31, while around 20 line trippings were reported in Magsaysay, Buenavista and Mobo since the installation last April 12 and 28.

"The improvement of the distribution system will greatly minimize the negative effects of line faults and will ultimately benefit the end-users," said DPC President Nestor D. Dadivas.

"We are working together with MASELCO in conducting further segment studies to identify other key areas in the distribution lines to improve the power supply reliability in the province," he added.

DMCI Power Corporation has a 15-year power supply agreement with MASELCO and is one of the major off-grid power producers in the Philippines.

####

### Other Relevant Information

None

### Filed on behalf by:

<b>Name</b>	Brian Lim
<b>Designation</b>	Vice President & Senior Finance Officer